ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
8

Ward Name
Kodigehalli

Street ID
W0567, W0559, W0553, W0547, W0539, W0537, W0546, W

Street Name
1st Crs, NA, 3rd Main Rd, 1st Main Rd

Significant Landmark
Devingara, Muneshwara Block, TATA Nagar and Kunnur

Segment No.
8/S-W0567/S121407

Total Length (m)
857.23

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	139.95	77.565793	13.048345	77.566682	13.047449	W0531	DEAD END
2	95.30	77.566502	13.048775	77.567290	13.048396	W0531	DEAD END
3	152.57	77.567429	13.047912	77.568715	13.047354	W0541	W0531
4	100.55	77.567504	13.048526	77.568353	13.048161	W0534	W0546
5	96.33	77.568966	13.048259	77.568599	13.047466	W0534	DEAD END
6	105.02	77.569549	13.048071	77.569165	13.047199	W0534	RI-A06
7	62.05	77.569941	13.047936	77.569883	13.047378	W0534	RI-A06
8	55.02	77.570270	13.047858	77.570215	13.047363	W0534	RI-A06
9	50.44	77.570556	13.047823	77.570531	13.047368	W0534	RI-A06

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads and Drain at Devingara, Muneshwara Block, TATA Nagar and Kunnuramma Temple in ward no 08 (Kodigehalli) Kodigehalli Sub-Division

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Improvements to Roads and Drain at Devingara, Muneshwara Block, TATA Nagar and Kunnuramma Temple in ward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone

Job No. / Work Code
008-14-000057

Work Order No.
EE/BTP/BBMP/KRIDL/WO/58/2014-15

Work Order Date
01/07/2014

Period of Extention
90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
01/07/2014	30/06/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Phone No.	E-Mail ID
9972039099	

Field Inspection Details

Number of Trees	Any Other Information	Name
15		srinivasa Murthy

Date of Inspection	Remarks
25/06/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0567, W0559, W0553, W0547,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/06/2016	25/07/2016	COMPLETED
SE	VASU K M	25/06/2016	25/07/2016	COMPLETED
EE	YARAPPA REDDY	25/06/2016	25/07/2016	COMPLETED
AEE	RAJANIKANTH	25/06/2016	25/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0567, W0559, W0553, W0547,

AE	SRINIVASA MURTHY	25/06/2016	25/07/2016	COMPLETED
AE	SRINIVASA MURTHY	25/06/2016	25/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0567, W0559, W0553, W0547,